

Figure 3.2. Fatigue cracking composite index for I-40, Wade Avenue, and I-440 sections.




Figure 3.3. Fatigue cracking results for US-70 sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.